## STEP BY STEP INSTRUCTIONS


1. Loop cable around components.

2. Insert cable through open hole.
Pull tight to temporarily secure cable.

3. Turn cable 180° and insert through final open hole. Pull tight to lock.

Min/Max Operating Temp: **-35°C/+75°C**

Loop Load Capacity: **40 lbs**

UV Light and Corrosion Resistant Non-Flame Propogating

Transport and store in original package

MADE IN THE USA